# Site Conditions – July 18, 2012

Aerial Photos courtesy John Luft, all locations are approximate


Willard Bay Outlet Channel
Willard Bay
BRMBR Unit 5C
PWRWWTP
New Pipeline Outfall


Willard Bay
Nutrient
Cycling
Study Site
Looking
north
BRMBR
Unit 5C

Harold Crane WMA

Willard
Bay



SAV & Surface
Algae

Mud Flats, Algae

Harold Crane WMA

GSLM

Site WS6 - 6” deep, turbid, SAV

Mud Bottom

Site WS8 – Shallow, SAV


Mud bottom, sparse SAV
GSLM
Site WS9
Water from O-line
Canal & 4s Drain